



Seattle Cement Plant 3801 E. Marginal Way South Seattle, Wash. 98134

January 27, 1984

Harbison Walker Refractories Attention: Mr. K. E. Sprong P. O. Box 1162 Bellevue, Washington 98009

SUBJECT: Quality Failure Nucon 60

Dear Sir:

With reference to Test Report 312021-2981 from Ohio State University, please be advised we are rejecting a lot consisting of eight pallets of Nucon 60. Please advise disposition, as they are occupying needed space in our brick storage area.

Also, please advise your intent to replace into our inventory or credit to our account.

Find enclosed a copy of our invoice from O.S.U. for testing which, due to product failure, should be at your cost.

Yours truly,

S. A. Webb Yard Foreman

SAW/mme Enclosure

cc: D. R. Donaldson W. N. Cunningham

> USEPA SF 1261089